

# Liberty

by



## Liberty Video Wall Presets Crestron Home Driver

### User Guide

### Product Manual

[Video Wall Presets Manual](#)

### Overview

Package name (pkg) : Extension\_Liberty\_IPEX5100\_IP.pkg

Version : 2.0.0

### Features

This driver provides the following functionality.

- Recall up to 6 video wall presets via Crestron home UI.
- Action to recall presets in sequence.

## Liberty Configuration

Prior to setting the driver up in Crestron Home ensure that the Liberty Arranger is fully configured and works correctly. Please refer to documentation provided by Liberty to setup the unit (link at top of document).

Once the Arranger is installed and setup add the Liberty AVSwitcher driver to crestron home and configure. Once this has been complete add the Video wall driver and configure.

When the video wall driver is configured you need to enter a friendly name and video wall name for each preset. The video wall name is the name configured in the Arranger. If you do not want a preset to display leave the friendly name blank.

## Support

If you require support for this driver please fill in a support request at <https://janustechnology.co.uk/support/>

Please ensure you provide the following information.

- Driver version you are using.
- Platform you are using e.g. Crestron Home
- Firmware version of your Liberty Video Wall Presets.
- Firmware version of your Crestron system.
- A full description of the issue you are having and how to recreate the issue.

## Troubleshooting

- Confirm that correct IP address is entered into the IP address field
  - Confirm that correct Port is entered (if required).
  - Check the Liberty Video Wall Presets can be pinged from the control system controller. If the ping fails check your network configuration and cabling.
  - For IP devices we recommend using a static IP address. Ensure this is done in either the device or router.
-

# Liberty Video Wall Presets Crestron Driver

## Release Notes

## Changes

Driver Release Version: 2.0.0 - Crestron Home Release

**2024-03-11**

### **Version Tested**

- Product Software: 4.3.6
- Product Control Server : 3.4.0.1
- Crestron Home Version : 3.020.0106

### **Enhancements**

- added 5100 Series
- added Icron Usb switching(SimplWindows Only)

### **Bug Fixes**

- NA

### **Exceptions**

- NA

### **User Impacted**

- NA
- 

Driver Release Version: 1.1.1 - Crestron Home Release

**2023-07-13**

## **Version Tested**

- Product Software: 4.3.6
- Product Control Server : 3.4.0.1
- Crestron Home Version : 3.020.0106

## **Enhancements**

- Changed DependencyGroup tag

## **Bug Fixes**

- NA

## **Exceptions**

- NA

## **User Impacted**

- NA
- 

## **Driver Release Version: 1.1.0 - Crestron Home Release**

**2023-06-30**

## **Version Tested**

- Product Software: 4.3.6
- Product Control Server : 3.4.0.1
- Crestron Home Version : 3.020.0106

## **Enhancements**

- Added Crestron Home Switcher Driver.
- Added Crestron Home Extension Driver.

## **Bug Fixes**

- NA

## **Exceptions**

- NA

## **User Impacted**

- NA
- 

## **Driver Release Version: 1.0.0 - Simpl Release**

**2023-06-27**

## **Version Tested**

- Product Software: 4.3.6
- Product Control Server : 3.4.0.1
- Crestron Series 4 Processor Firmware: 2.8001.49
- Simpl Windows: 4.25
- Device Database: 200.275 (build: 200.27500.001.00)
- Crestron Database: 219.00 (build: 219.0000.002.00)
- Crestron Toolbox: 3.12p50 (build: 3.1250.0002.0)
- SIMPL+ Cross Compiler: 1.3

## **Enhancements**

- Initial Driver Release

## **Bug Fixes**

- NA

## **Exceptions**

- NA

## **User Impacted**

- NA
-